

Ethernet users: Upgrade your firmware to V1.6 now!

The annoying bug in the firmware that had rendered the Ethernet interface almost useless has finally been fixed.

In order to upgrade your 1541 Ultimate Ethernet to version 1.6, download the following zip file:

[1541 Ultimate V1.6 Firmware Download](#)

Installation instructions:

- 1) Make sure that in your current configuration, the "application to boot" is set to "appl.bin" (the default).
- 2) Unzip the zip file into the ROOT of an SD-card, of which you have made sure that the 1541 Ultimate can read it.
- 3) Place the SD-card in the 1541U, and make sure the 1541U is correctly inserted in a C64/C128 expansion slot.
- 4) Turn on the C-64 and watch the screen output.
- 5) Turn off the C-64 when the update is finished.

In comparison to 1.5, the following has been fixed:

- Reads from the Ethernet chip have been fixed. The unit now correctly receives packets.

Other known issues in 1.5 are also still present in 1.6.

For trying this version temporary, download the appl.bin file [here](#) and place it in the root of the SD-card. The 1541 Ultimate will boot this file. When you remove the file again, you will be back to your current version (=V1.5!).